

## BIOS Revision Notes

Target Board-Name: PCM-VDX-2-512  
Target Board-Number: 373

### Change History Log:

Note: The Min. PCB Rev Rqd field specifies the minimum PCB Revision and assumes all current ECO's have been applied.

Date	Time	Version	CKSM	Min. PCB Rev Rqd	Description
12/20/2010	12:00:44	37310351-2	8723h	D	Original Release
04/06/2011	08:04:04	37311096-2	FD85h	D	Enabled 220-227h I/O range to LPC
04/25/2011	09:32:08	37311115-2	1C89h	D	Removed IRQ14 from PnP IRQ list
					Removed OnBoard Virtual Flash FDD menu item
08/29/2011	07:49:41	37311241-2	2ACCh	D	Disabled 338-33Fh I/O range to LPC
03/16/2012	12:42:03	37312076-2	3540h	D	ECO#12-54
					Moved CMOS locations of COM modes and WD Timer for proper restore with no battery
08/21/2012	13:59:36	37312234-2	780Eh	D	ECO#13-22
					Hid North Bridge Configuration menu selection
03/20/2014	09:44:51	37314079-2	5DF4h	D	ECO#14-27
					Rearranged COM3 and COM4 address selections - fixed problem with console use of COM3/4